

# SURVEY RECOVERY FORM

City of Everett  
Department of Public Works

State of Washington  
County: Snohomish

Station Name: 631 53 01

Horizontal Datum: NAD 83/91

Vertical Datum: NAVD 88

Control Point ID: Book: 631 Page: 53 Pt#: 01

Established By: WJA

Date: 10/26/95

Revised 1/24/01

Section: 7

Township: 28 N

Range: 5 E

LATTITUDE: (5 decimal places) 47 55 33.54236

LONGITUDE: (5 decimal places) 122 12 34.77690

ORTHOMETRIC HEIGHT: 446.51 Feet

136.096 Meters

## Washington State Plane Coordinates – North Zone

Edited by Geodetic Consultants in 1996, revised 5/5/97 and 02/15/01.

	Northing (4 decimal places)	Easting (4 decimal places)	Point Scale Factor (to 9 decimal places)	Convergence Deg Min Sec
Feet	340787.694	1302999.811	0.999947840	-01 01 28.9
Meters	103872.2969	397155.1367		

### HORIZONTAL DATA:

Horizontal position established by: WJA

☐ resection survey, comments

☒ GPS survey, GPS adjustment software used: Leica rapid static GPS and Leica SKI adjustment software

☐ other, explain:

surveyor's estimated relative positional accuracy:      .01 ft. @      95% confidence

surveyor's estimated absolute positional accuracy:      .05ft. @      95% confidence

### VERTICAL DATA:

Vertical position established by: Pertect

☒ differential leveling to: 3 order accuracy

☐ GPS survey, accuracy within      ft      meters

surveyor's estimated relative positional accuracy:      ft @      % confidence

surveyor's estimated absolute positional accuracy:      .03ft @      95% confidence

## MONUMENT DESCRIPTION

**A 4-inch diameter iron pipe with a lead plug and brass tack in an iron monument box.**

## TO REACH

**Located on Beverly Boulevard, north of the intersection of Florida Drive, south of Leland Drive.**

## REFERENCES

Az from North	Distance	Reference Description
---------------	----------	-----------------------

Month & Year Recovered:  
09/2000

Condition of Mark:  
GOOD

Recovered By:  
Pertect Engineering Inc.